

ROUTE 104 RECONSTRUCTION - WEST RIDGE ROAD

Greece, New York

Passero Associates provided construction inspection for five miles of a six-lane highway with the demolition of 18 existing structures and construction of 16 new bridges.

Inspection duties included earthwork, drainage, paving, concrete, barriers, curbing and sidewalk. There was record keeping by the MURK System and Cees, final quantities, as-built drawings and final package information prepared by our staff.

Client:
NYSDOT

Construction Cost:
\$23,000,000

Completion Date:
November 2004

Services Provided:
Construction Inspection
Contract Administration
Permit Approvals
Underground and Area
Utility Coordination
Community Liaison
Work

APWA Project of the Year Award Winner

